

Shortcut Keys

For mouseless operation, use keyboard shortcuts to start commands for selected items and change some system settings. Following are the shortcut assignments for PADS Logic.

Control Key Shortcuts

Shortcut	Description
Ctrl+B	View sheet
Ctrl+C	Copy
Ctrl+D	Redraw
Ctrl+E	Move selected object(s)
Ctrl+F	Flip selected on X axis
Ctrl+N	New file
Ctrl+O	Open file
Ctrl+P	Print/Plot
Ctrl+Q	Query/Modify
Ctrl+R	Rotate selected
Ctrl+S	Save
Ctrl+V	Paste
Ctrl+W	View Zoom mode
Ctrl+X	Cut
Ctrl+Alt+C	Display Colors Setup
Ctrl+Alt+E	View Extents
Ctrl+Alt+G	Preferences
Ctrl+Alt+M	Toggle menu bar
Ctrl+Alt+P	View Previous
Ctrl+Alt+S	Status Window
Ctrl+Tab	Cycle Alternate Gate Decals
Ctrl+PageDown	Reset delta coordinates to measure from current position
Shift+Ctrl+D	Draw Group while in Move Group Mode
Shift+Ctrl+F	Flip selected on Y axis
Shift+Ctrl+P	Record prompt windows toggle (macros)

Function Key Shortcuts

Shortcut	Description
F1	Help
F2	Add Connection
F8	Mouse move compression (macros)
F9	Absolute/Relative coordinates toggle (macros)
F10	End recording (macros)

Other Key Shortcuts

Shortcut	Description
BackSpace	Remove last connection corner
Esc	Cancel command
M	Right mouse click
Spacebar	Left mouse click
Alt+Spacebar	Add Offpage while in Add Connection mode
Shift+Spacebar	Add Power Symbol while in Add Connection mode
Ctrl+Spacebar	Add Ground Symbol while in Add Connection mode

Related Topics

 [Modeless Commands](#)